



Stone Refinishing Project



Location: Kansas City, MO
Type of Stone Floor: Terrazzo

High profile office building near the Country Club Plaza increases occupant satisfaction with shiny floors.

Problem: Acidic or high alkaline products were left on the stone floor causing etching to the floor.

Solution: KC Restoration honed and polished the floor to remove etching and provide *Cleaning and Care* instructions to share with building and janitorial teams working on the floor.