



# Stone Refinishing Project



**Location:** Kansas City, MO  
**Type of Stone Floor:** Terrazzo

High profile office building near the Country Club Plaza increases occupant satisfaction with shiny floors.

**Problem:** Acidic or high alkaline products were left on the stone floor causing etching to the floor.

**Solution:** KC Restoration honed and polished the floor to remove etching and provide *Cleaning and Care* instructions to share with building and janitorial teams working on the floor.