



Patina Refinishing Project



Location: Overland Park,
Kansas

Client: Newmark Zimmer

Type of Metal: Brass

KC Restoration created a clean and modern look for this large office building in Overland Park.

Problem: Elevators had a dated look, were scratched, and needed cleaning.

Solution: KC Restoration cleaned, reglazed, and applied a patina to the elevator fronts to change the look from a dated to a clean and modern finish.