



Exterior Deep Cleaning Project



Location: Kansas City, Missouri

Types of Surfaces: Limestone, Granite and Brick

The iconic Russell Stover chocolate company's headquarters near the Country Club Plaza needed a refreshed exterior look. Over 34,000 sq ft of limestone, brick, and granite had become extremely stained from several years' accumulation of exterior contaminants.

Problem: Build-up of outdoor pollutants and other biological growth caused dark staining of the facility's exterior.

Solution: KC Restoration performed deep exterior cleaning services to restore this weathered façade to a fresh and rejuvenated look. Dirt, pollution, and biological staining were removed while protecting the surrounding vegetation.