



# Patina Refinishing Project



**Location:** Overland Park, Kansas

**Client:** Newmark Zimmer

**Type of Metal:** Brass

KC Restoration created a clean and modern look for this large office building in Overland Park.

Problem: Elevators had a dated look, were scratched, and needed cleaning.

Solution: KC Restoration cleaned, reglazed, and applied a patina to the elevator fronts to change the look from a dated to a clean and modern finish.